




HEALTH Community & Emergency Services

South 1 Environmental Health Services

32 Marlborough Avenue

Widenham, Umkomaas

4170

Tel: 039 973 0850

www.durban.gov.za



Our Reference : 30/2/2/1

Enquiries : J. S. Masinga

Joyman.masinga@durban.gov.za

Mr D. de Klerk
Tetelestai Recovery Centre
5 Beach Road
Winkelspruit
KINGSBURGH

Date: 1 July 2022

HAND DELIVERY

Dear Sir

INSPECTION REPORT OF TETELESTAI RECOVERY CENTRE AT 5 BEACH ROAD WINKELSPRUIT IN KINGSBURGH - WARD 97 - eTHEKWINI MUNICIPALITY

The above-mentioned Rehabilitation Centre was inspected on the 30th of June 2022 in terms of National Health Act 61 of 2003, National Building Regulations and Standards Act (Act 103 of 1977), eThekweni Municipality Public Health Bylaws.

1. Administrative Section

- The centre has offices and 11 Staff members 7 (seven) females and 4 (four) staff members.

2. Enrolment

- The centre has an enrolment of 53 admitted patients 14 (fourteen) females and 39 (thirty-nine) males.
- They can accommodate a maximum of 150 patients.

3. Yard Condition

- The yard was well maintained with paving on the drive-way and green grass on other section. The facility has swimming pool which is adequately secured.

4. Sanitation Station

- The facility has adequate ablution facilities for staff and patients, with sufficient wash-hand basins along the aqua-privies (water-borne toilet system);
- By the dormitories bathtubs and showers are in place with cold and hot water supply.

5. Dormitories

- The dormitories were divided into two levels, with female side on the ground floor and male part on the basement
- They were spacious with adequate aeration and illumination (in accordance Building Regulation i.e. 10% of floor area for light and 5 % of the openable window-side).
- They had adequate beds and linen for patients.
- There were small fridges and microwaves in each dorm.

6. Kitchen Facilities

- Tetelestai Centre has the state-of-the-art kitchen, with all facilities as stipulated in the Regulation 638 of the Food Act (FCD Act of 1972 as amended) – Certificate of Acceptability had been granted to the centre.

7. Amenities

- The facility has communal hall which also serves as a dining hall.
- There are extra recreational and educational activities that are run by the centre for patients.

8. Safety

- The facility has serviced fire extinguishers at strategic points.
- It is fenced around with one (1) automated gate.

9. Refuse Removal System

- The facility is contracted to Cleansing and Solid Waste Department of eThekweni for refuse removal. Waste is collected twice a week.
- Each dormitory had its small bin which is decanted to the bigger wheely bins in turn.

10. Recommendation

The facility is run efficiently and effectively. It is health and environmental compliant. This department has no reservation in granting Tetelestai Recovery Centre the permit.

Yours faithfully


J S Masinga
SENIOR ENVIRONMENTAL HEALTH PRACTITIONER


Mrs S P N Myeza
SOUTH 1 EHS MANAGER

cc Welfare and Social Development Department